
•	NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
1	Windham Congregational Church	1323 - 1	71-A-5	
2	Baptist Church	1323 - 2	71-A-5	
	•	141		
			-	
****			15	
	•			
-				
-	•		į.	
-				
-				
		, , ,		
•				
4			-	
-		2		



	SURVEY NUMBER:
	NEGATIVE FILE NUMBER:
front. 3-tier steeple; lat and Eud tiers	14 C-642-642-65
STATE OF VERMONT	LATITUDE LONGITUDE
Division of Historic Sites	
Montpelier, VT 05602	
	43 10' 51" 72 43' 35"
HISTORIC SITES & STRUCTURES SURVEY	
Individual Structure Survey Form	U.S.G.S. QUAD MAP: axton's River Quad., 15' series
Tal.	
COUNTY:Windham	PRESENT FORMAL NAME:
TOWN: Windham	
LOCATION:	ORIGINAL FORMAL NAME:
Windham Village	PRESENT USE: church
FUNCTIONAL TYPE: church	ORIGINAL USE: church
COMMON NAME: Windham Congregational Chur	GhARCHITECT/ENGINEER:
OWNER: Windham Congregational Church	
ADDRESS:	BUILDER/CONTRACTOR:
AAAAAAA AAAAA AAAAAAAAA	
ACCESSIBILITY TO PUBLIC: Yes □ No □ Restricted ☒	PHYSICAL CONDITION OF STRUCTURE:
LEVEL OF SIGNIFICANCE:	Excellent Good Fair Deteriorated
Local State National	THEME:
DATE BUILT: 1802	STYLE:
GENERAL DESCRIPTION:	
Structural System	
	e 🖺 Concrete 🗆 Concrete Block 🗆
2. Wall Structure a. Wood Frame: Balloon	Western Platform D Post & Beam
	Brick Stone Concrete
Concrete Block	Direct D Concion D
c. Iron 🗆	
d. Steel	
e. Other:	Ward Chinala D Band C Batter D
Shinlan Novelty Str	Wood Shingle ☐ Board & Batten ☐ acco ☐ Tile ☐ Brick ☐ Stone ☐
Slate Sheet Metal St	Paper [
4. Roof Structure	apor L
a. Truss: Wood 🗆 Iron 🗆	Steel □ Concrete □
b. Vault: Brick Stone	□ Concrete □
c. Other:	Annhala Chinala D mila D
Metal Shingle Slate	le Asphalt Shingle Tile
6. Engineering Structure:	Sheet Metal Paper
7. Other:	
Appendages: Porches Towers	Dormers Bay Windows Ells
1Chimneys Cupolas □ Wings □	Sheds Other: steeple
Number of Stories: 2	Bueepie
Approximate Dimensions:	
Helm Jerkinhead Monitor [Flat Shed Hip Mansard Save Tooth Revend
neim - Serkinnead - Monitor (J Saw Tooth Round
Chester W. Diebs	
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat	Positive Negative Mixed
Other:	Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:


Open wooden porch without roof across front. 3-tier steeple; 1st and 2nd tiers square, 3rd tier is spire.

RELATED STRUCTURES:

STATEMENT OF SIGNIFICANCE:

Dominant visual landmark of village. "Town Office" and "Town Hall" now occupy first floor of building.

SURROUNDING ENVIRONMENT: MAP: (Indicate North In Circle) Open Land X Woodland Scattered Buildings X N Moderately Built Up Densely Built Up Residential X Commercial Agricultural Industrial F Other: ROUTE RECORDED BY: Chester H. Liebs ORGANIZATION: Vermont Division of Historic Sites DATE RECORDED: 11/3/71



WID-R-1

VERMONT DIVISION OF HISTORIC SITES
1.1. Alexander 1) in de an
TOWN VOICE
SUBJECT Windham Congregations Chim
DATE 1 77 FILE # 77 1-4-5
CREDIT CHESTER H. LIEBS
WEW Looking N

1323-1

	SURVEY NUMBER: 1323-2	
bond. Atomes in side recessed for wir-	NEGATIVE FILE NUMBER: 71-A-5	
0/20. Readen in betien queins. 2 that		
STATE OF VERMONT	LATITUDE LONGITUDE	
Division of Historic Sites Montpelier, VT 05602	43 07' 45" 72 42' 42"	
HISTORIC SITES & STRUCTURES SURVEY	Parara e which is now lown al	
Individual Structure Survey Form	U.S.G.S. QUAD. MAP:	
COUNTY: Windham	Saxton's River Quad., 15' series PRESENT FORMAL NAME:	
TOWN: Windham		
LOCATION:	Baptist Church ORIGINAL FORMAL NAME:	
South Windham	Baptist Meeting House	
Botton willtain	PRESENT USE: church	
FUNCTIONAL TYPE: church	ORIGINAL USE: church	
COMMON NAME: Baptist Church	ARCHITECT/ENGINEER:	
OWNER: So. Windham Baptist Church		
ADDRESS:	BUILDER/CONTRACTOR:	
ACCESSIBILITY TO PUBLIC:	PHYSICAL CONDITION OF STRUCTURE:	
Yes □ No □ Restricted ☒	Excellent Good Good	
LEVEL OF SIGNIFICANCE:	Fair Deteriorated	
Local 🗷 State 🗆 National 🗆	THEME:	
DATE BUILT: 1825	STYLE: Greek Revival	
GENERAL DESCRIPTION: Structural System		
b. Load Bearing Masonry: Concrete Block c. Iron d. Steel e. Other: 3. Wall Covering: Clapboard Shiplap Novelty Slate Sheet Metal 4. Roof Structure a. Truss: Wood Iron b. Vault: Brick Stone c. Other: 5. Roof Covering: Wood Shings Metal Shingle Slate 6. Engineering Structure: 7. Other: Appendages: Porches Chimneys Cupolas Wings Number of Stories: 1 Approximate Dimensions:	Steel	
THREAT TO STRUCTURE: No Threat Zoning Roads Development Deterioration Cother:	LOCAL ATTITUDES: Positive Negative Mixed Other:	

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Side and rear elevations brick, running bond. Arches in side recessed for windows; front frame and clapboard. Sash 20/20. Wooden imitation quoins. 2 tier steeple and spire


RELATED STRUCTURES:

Parsonage which is now Town Clerk's Office.

STATEMENT OF SIGNIFICANCE:

Church represents an interesting variation on the vernacular Greek Revival theme through the use of both brick and clapboard. The recessed arcaded wall treatment is found in various domestic building types throughout Eastern Vermont as far North as Chester between the years 1814 and 1830.

MAP: (Indicate North In Circle)	Open Land
PARSONAGE	RECORDED BY: Chester H. Liebs
	ORGANIZATION: Vermont Division of Historic Sites
SOUTH WINDHAM	DATE RECORDED: 11/3/71



W1D-R-2 1323-2

VERMONT DIVISION OF HISTORIC SITES
COUNTY Windleam TOWN Columbia
SUBJECT Babtest Church
DATE 1/17/ FILE #71-A-S
CREDIT CHESTER H. LIEBS
VIEW Looking N