Member: Windham Town

Visit Date: 04/26/2018

NO PHOTO TAKEN

Consultant: Wade Masure

Location: Town Garage

Location Detail: Throughout garage and drill press

Priority: LOW

Suggested Correction Date: 07/25/2018

Status: Open



Hazard: An extension cord was being used in lieu of permanent wiring

permanent wiring.. All electrical work must be performed by a licensed electrician. permanent wiring. Install an outlet for this piece of equipment or where extension cords are currently in use as Recommendation: Extension cords shall only be used for temporary wiring and shall not be substituted for

Location: Town Garage

Location Detail: First Aid Kit

Priority: LOW

Suggested Correction Date 07/25/2018

Status: Open



NO PHOTO TAKEN

Hazard: Some items within the first aid kit were in use past their expiration date

The state of the s to provide guidance on what types of items should be included in the kit, for your location and operation. within their expiration date and that it is otherwise appropriately equipped. A local healthcare provider may be able Recommendation: Remove the outdated items and periodically check the first aid kit to make sure that all items are

Member: Windham Town Visit Date: 04/26/2018

Location: Town Garage Location Detail: Cold Storage building

Suggested Correction Date: 07/25/2018

Hazard ID: 2203 Priority: LOW Status: Open

Hazard: A GFCI that was present was damaged or inoperable. Recommendation: Replace the damaged/inoperable GFCI with a new ground fault protected outlet and cover. A

licensed electrician shall perform all electrical work. This is at the cold storage building.

Location: Town Garage Location Detail: Liquid Chloride Tank

Hazard ID: 2204 Priority: LOW Suggested Correction Date: 07/25/2018 Status: Open

The War Hazard: Certain containers of hazardous chemicals were not labeled with the product name and appropriate hazard warning information.

the global harmonized system. This is in regards to the outside liquid chloride tank. Recommendation: Label each secondary container of hazardous material with an appropriate label that adheres to



Consultant: Wade Masure

NO PHOTO TAKEN



NO PHOTO TAKEN

guarantee the fulfillment of your obligation under local, state, or federal laws or regulations. When recommendations have been completed, please let us know. Note: all "High Priority" losses. Recommendations are developed from the conditions observed at the time of the survey and may not include every possible cause of loss. Compliance with these recommendations does not Our service visits are designed to assist you in your loss control efforts. We do not assume responsibility for the discovery or elimination of all hazards which could possibly cause accidents or recommendations must be completed prior to being considered for a PACIF Equipment Grant "award".

Member: Windham Town

Visit Date: 04/26/2018

Consultant: Wade Masure

NO PHOTO TAKEN

Location: Town Garage

Location Detail: Cold Storage Area

Hazard ID: 2207

Priority: LOW

Suggested Correction Date: 07/25/2018

Status: Open

Hazard: An extension cord was being used in lieu of permanent wiring.

cold storage area should be removed. Recommendation: Extension cords shall only be used for temporary wiring, the extension cord to the lite in the NICCHISCO GLECT



Location: Town Garage

Priority: LOW

Hazard ID: 2208

Location Detail: Mezzanine Area

Suggested Correction Date: 07/25/2018

Status: Open

Hazard: Stored items are disorganized and the area has significant clutter that creates egress challenges and trip/fall

NO PHOTO TAKEN

TANK. Recommendation: Reduce storage and organize remaining items. Maintain clear paths of travel within the facility.

Member: Windham Town

Visit Date: 04/26/2018

Consultant: Wade Masure

NO PHOTO TAKEN

Location: Town Garage

Hazard ID: 2224

30 TO

reduce the potential for backing claims.

Priority: LOW

Location Detail:

Suggested Correction Date: 07/25/2018

Hazard: Trucks, heavy equipment and other large vehicles were not equipped with back up cameras that could

Status: Open

**Recommendation:** Equip back up cameras on vehicles that have limited rear view. The truck involved in the backing incident dated 1/22/18 is not equipped with a back up camera.

Location: Town Garage

Location Detail: Truck Bays

Suggested Correction Date: 07/25/2018 Status: Open

NO PHOTO TAKEN

Hazard ID: 2209 Hazard: Outlets in an automotive garage were not GFCI protected

Priority: LOW

accomplished at the outlet or at the panel breaker. All electrical work must be completed by licensed electrician. Although some outlets were GFCI protected there appeared to be some that were not or were not functioning Recommendation: All electrical outlets in an automotive garage must be protected by GFCIs. This may be

guarantee the fulfillment of your obligation under local, state, or federal laws or regulations. When recommendations have been completed, please let us know. Note: all "High Priority" recommendations must be completed prior to being considered for a PACIF Equipment Grant "award". losses. Recommendations are developed from the conditions observed at the time of the survey and may not include every possible cause of loss. Compliance with these recommendations does not Our service visits are designed to assist you in your loss control efforts. We do not assume responsibility for the discovery or elimination of all hazards which could possibly cause accidents or

Member: Windham Town

Visit Date: 04/26/2018

Consultant: Wade Masure

NO PHOTO TAKEN

Location: Town Garage

Hazard ID: 2221

Priority: LOW

Location Detail:

Suggested Correction Date: 07/25/2018

Status: Open



Cox Hazard: Light switches and/or outlets were damaged

regards to the outlet for the pressure washer Recommendation: Repair the switches/outlets. All work must be completed by a licensed electrician. This is in

Location: Town Garage

Location Detail: Office area

Priority: MEDIUM Suggested Correction Date: 06/25/2018

Hazard: An extension cord was being used in lieu of permanent wiring.

NO PHOTO TAKEN

Status: Open

approved permanent wiring. permanent wiring. The extension cord providing power to the office area should be removed and replaced with Recommendation: Extension cords shall only be used for temporary wiring and shall not be substituted for

guarantee the fulfillment of your obligation under local, state, or federal laws or regulations. When recommendations have been completed, please let us know. Note: all "High Priority" recommendations must be completed prior to being considered for a PACIF Equipment Grant "award". losses. Recommendations are developed from the conditions observed at the time of the survey and may not include every possible cause of loss. Compliance with these recommendations does not Our service visits are designed to assist you in your loss control efforts. We do not assume responsibility for the discovery or elimination of all hazards which could possibly cause accidents or

Page 12 of 15