

Vermont Department of Public Safety

IVISION OF FIRE SAFET



Site Id: 42496

Office of the State Fire Marshal, State Fire Academy and State Haz-Mat Team

firesafety.vermont.gov

☐ Waterbury Regional Office 45 State Drive Waterbury, VT 05671-8200 [phone] 802-479-4434 [fax] 802-479-4446

☐ Rutland Regional Office 56 Howe Street, Building A, Suite 200 Rutland, VT 05701-3449 [phone] 802-786-5867 [fax] 802-786-5872

☐ Williston Regional Office 380 Hurricane Lane, Suite 101 Williston, VT 05495-2080 [phone] 802-879-2300 [fax] 802-879-2312

☑ Springfield Regional Office 100 Mineral Street, Suite 307 Springfield, VT 05156-3168 [phone] 802-216-0500 [fax] 802-216-0511

FIRE INSPECTION RESULTS

Structure Information

WINDHAM MEETING HOUSE- FORMERLY Name:

CONGREGATIONAL CHURCH

Structure Id: 42496

WINDHAM, VT 05359

Business Owner

WINDHAM CONGREGATIONAL CHURCH (N Name:

Address:

Address:

26 HARRINGTON RD

WINDHAM, VT 05359

26 Harrington Rd

Building Description

Risk Index: Smoke Det:

Const Type: 5A CO Detect: Occ Type: A4 Fire Alarm: Occupants: Stand Pipe:

Sprinkler:

Units:

2 Floors: Sq Feet: 960

Project Description

Name: finsp

Type: **Building Project** Received: 01/27/2020

Yes

Workitem Id: 446114

Inspection Detail

Insp Date: 06/20/2024 Insp Type: Occ Granted: Follow-up Conditional

Violations:

Limited

Hazard Index:

Level 2

Inspector: PATRICK BANKS (S 100237)

Violations and Notes

Comply By:

I met with Jenna (Preservation Trust of VT), Caitlin (State of VT Tax credits), and Cathy and Tom (owner reps) to review this space regarding front doors and kitchen.

Per the 1/24/23 inspection report, events are allowed on the second floor with the following conditions:

- 1) The ground level doors must swing in the means of egress (see below). The current proposal is to change the door swing with new doors and maintained the required clear width of 32 inches. Any doors from the second level and ground level to the outside shall have listed panic hardware if a latch is provided on the door.
- Events shall be limited to no more than 20 times a year.

Future inspection will be required prior to September event to determine occupant loads.

Other items noted:

Per NFPA 96, Residential equipment can be used with approval by this office without the commercial hood system. This approval will be granted with the following conditions:

- 1) K-Class fire extinguishers are installed in the space by a certified fire extinguisher company.
- 2) Only residential equipment remains to be used for cooking.

Any future ramp/door upgrades will need a construction permit from this office.

For the Division of Fire Safety,

Patrick Banks 802-503-2696